## MONTANA DEPARTMENT OF TRANSPORTATION RESEARCH PROGRAM HELENA, MONTANA 59620-1001

Two Medicine Bridge RTF-STPHS 1-3(22)2 10 Annual Report September, 1999

This Project involved placing a waterproof membrane (PavePrep®) and a 0.15 ft. thick plant mix overlay on the deck of the existing Two Medicine Bridge. This was to preserve the deck from further deterioration and maintain a decent riding surface until replacement of the bridge by the year 2005. This project is located on NINHS P-1, US-2 approximate milepost 210 in Glacier County on the Blackfeet Indian Reservation.

The Research Management Unit (RMU) classified this project as formal through the year 2002 with possible extension of the evaluation period.

Rutting data is as follows. Eastbound section outer wheel path (OWP) rut depth was averaged at 5.3mm, with a standard deviation (STD) of 1.2, compared to the inner wheel path (IWP) at 2.7mm with a STD of 1.1. Westbound OWP rut depth averaged 3.0mm with a STD of 1.5, compared to the IWP of 2.0mm with a STD of 1.0.

Rut measurements were taken from the wheelpaths. However, the overall appearance of the rutting seemed to be a bathtub in nature across the lane. Transverse cracking at the east end approach is indicating movement of the bridge.